

ID	Location	Owner	Type of Defence	Length (m)	Current S.o.P.	Beach Level (m AOD)	Front seawall level (m AOD)	Rear seawall Level (m AOD)	Condition
1	Sportsman to Red Sluice	EA	Concrete Seawall	1343	1:100	3.8	6.5	N/A	Fair to good
2	Red Sluice to Blue Anchor	EA	Clay bund	761	1:50	4.0	N/A	5.3	Fair
3	Faversham Road	EA	Clay Bund	790	1:50	N/A	N/A	5.3	Fair
4	Preston Parade West	CCC	Concrete seawall	621	1:200	4.0	5.2	N/A	Very good
5	Preston Parade East	CCC	Concrete seawall	387	1:200	4.0	5.2	N/A	Very good
6	Admiralty Walk	CCC	Concrete seawall	455	1:200	4.0	5.1	N/A	Very good
7	Whitstable	Railtrack	Concrete revetment	149	1:200	4.0	3.3	N/A	Fair
8	Golf Club wall	CCC	Concrete seawall & rear wall	421	1:200	4.0	4.9	5.6	Very good
9	West Beach	CCC	Concrete seawall & rear wall	408	1:200	4.7	4.9	5.8	Very good
10	Whitstable Central Area West	CCC	Concrete seawall & rear wall	439	1:200	4.7	4.9	5.8	Very good
11	Whitstable Central Area East	CCC	Concrete seawall and rear wll	626	1:200	4.7	4.9	5.8	Very good
12	Whitstable Harbour	CCC	Concrete seawall / various buildings	482	1:200	4.7	4.8	5.8	Fair to good
13	Harbour Beach	CCC	Concrete seawall & rear wall	280	1:200	4.7	4.3	5.8	Very good
14	Beach Walk	CCC	Concrete seawall	366	1:200	4.7	5.2	N/A	Very good
15	Tankerton Beach West	CCC	Concrete seawall	1610	1:200	4.7	5.9	N/A	Very good
16	Tankerton Beach East	CCC	Concrete seawall	695	1:200	4.7	5	N/A	Very good
17	Longrock	CCC	Clay bund	639	1:100	4.2	5.2	N/A	Very good
18	Swalecliffe	CCC	Concrete seawall & rear wall	711	1:200	4.8	5.1	6.7	Very good
19	Studd Hill	CCC	Concrete seawall & rear wall	1063	1:100	4.0	5.7	6.3	Fair
20	Hampton Bay	CCC	Concrete seawall & rear wall	235	1:100	3.25	4.8	6	Fair
21	Hampton Pier	CCC	Concrete seawall & rock armour	380	1:100	4.3	4.85	5.3	Good
22	Westcliff	CCC	Concrete seawall + KCC rear wall	1273	1:100	5.0	5.45	6.9	Good
23	Lane End	CCC	Concrete seawall	265	1:100	4.6	4.8	5.7	Very good
24	Herne Bay Central	CCC	Concrete seawall & apron + rear wall	549	1:200	4.6	5.1	5.9	Very good
25	Herne Bay Breakwater	CCC	Rock Armour	595	1:200	N/A	N/A	3.8	Good
26	Coopers Hill	CCC	Concrete seawall & apron + rear wall	489	1:100	2.7	4.9	6	Good
27	East Cliff I	CCC	Concrete seawall + rear wall	865	1:100	3.5	4.1	6.5	Good
28	Queens Avenue	CCC	Concrete seawall & apron + rear wall	226	1:100	3.4	4.8	6	Good

ID	Location	Owner	Type of Defence	Length (m)	Current S.o.P.	Beach Level (m AOD)	Front seawall level (m AOD)	Rear seawall Level (m AOD)	Condition
29	East Cliff II	CCC	Concrete seawall & apron + rear wall	686	1:100	4.1	4.85	6.7	Good
30	Hillborough Cliff	CCC	Concrete seawall & apron + rear wall	658	1:100	4.1	4.85	6.3	Good
31	East Cliff III	CCC	Rock Revetment	372	1:100	N/A	6	N/A	Fair
32	Reculver Country Park	CCC	Undefended	1427	N/A	N/A	N/A	N/A	N/A
33	Reculver west wall	CCC	Concrete seawall & apron + rear wall	218	1:100	N/A	5.4	6.4	Good
34	Reculver rock revetment	EA	Concrete seawall & rock revetment	205	1:100	N/A	5.4	6.4	Very good
35	Reculver Towers	EH	Blockwork apron & toe rock	210	1:100	N/A	6	N/A	Fair to good
36	Reculver east wall	CCC/EA	Concrete seawall & rock revetment	126	1:100	N/A	6.9	N/A	Very good
37	Northern seawall	EA	Concrete seawall & apron + upstand wall	4539	1:100	4.5	6.7	N/A	Good