

ID	Type of Flooding	Date Flooded	Description of Flooding
1	Sea	1996	Some overtopping occurred at the eastern end but this was minimal. One property was flooded due to seepage through the shingle full and some 2,000 tonnes of shingle were lost.
2	Fluvial	Ongoing	One property and the gardens of various other properties in Church Lane, Freemans Close and Faversham Road flood. Gardens only flood 2-3 times a year. Property floods once every 2 years. Seasalter Cross, Whitstable.
3	Fluvial	Ongoing	One property and the gardens of various other properties in Church Lane, Freemans Close and Faversham Road flood. Gardens only flood 2-3 times a year. Property floods once every 2 years. Seasalter Cross, Whitstable.
4	Fluvial	Ongoing	One property and the gardens of various other properties in Church Lane, Freemans Close and Faversham Road flood. Gardens only flood 2-3 times a year. Property floods once every 2 years. Seasalter Cross, Whitstable.
5	Fluvial	Ongoing	One property and the gardens of various other properties in Church Lane, Freemans Close and Faversham Road flood. Gardens only flood 2-3 times a year. Property floods once every 2 years. Seasalter Cross, Whitstable.
6	Surface Water	Ongoing	Surface water runs onto highway. Water from forecourt of Public House. A299 - Wraike Hill.
7	Fluvial	Ongoing	Flooding of Denstroude Lane due to surcharge of culvert and ditch.
8	Surface Water	Unknown	Surcharge of culvert and surface water sewers. Old Red Lion Bridge - Whitstable boundary A290.
9	Surface Water	Ongoing	Surface water runs onto highway. Water from Banks and verges, drainage is by a sewer. A299, Golden Hill, Millstrood.
10	Surface Water	Ongoing	Continuous flooding of gardens during wet winters. Caused by water running off the Sir William Nottidge School playing fields. Linden Avenue Whitstable.
11	Highway	Ongoing	Sunken road floods, A299 service road.
12	Fluvial	2000	Repeated flooding of property from the Swalecliffe Brook. The property is very Vulnerable, a rise in water level posing a serious threat to 56 Herne Bay Road.
13	Fluvial	Ongoing	Flooding of urban development, gardens adjacent to brook and South Street Road. Gardens flood once a year, South Street every 2 years.
14	Highway	Ongoing	Dished road under railway bridge. A299 - Chestfield roundabout.

15	Fluvial	2000	Flooding of gardens caused by an inadequate culvert and ditch. Maydowns Road Chestfield.
16	Fluvial	Ongoing	Flooding of Thanet Way every four years. Caused by inadequate culverts under the Thanet Way and adjacent railway line.
17	Fluvial	Ongoing	Flooding of Colewood Road, Swalecliffe, every four years, caused by an inadequate sewer.
18	Fluvial	2000	Flooding of land around the caravans at Sea View Caravan camp, Colewood Road, Whitstable. Occurs when peak flows in the watercourse coincide with the outfall being tide locked.
19	Highway	Ongoing	Flooding of Daimler Avenue, Herne Bay and some urban development. Happens approx. twice a year.
20	Highway	Ongoing	Flooding of Whitstable Road/Sea Street, Herne Bay and some urban development. Happens twice a year.
21	Fluvial	2000	Private watercourse floods Cherry Gardens
22	Fluvial	2000	Private watercourse floods Eddington Lane
23	Sea	1995	Prolonged NE gale/gale force winds, large hole in the Northern Sea Wall near Reculver Towers. Further severe damage to a 150m length of the sea wall due to severe undercutting. Access road to oyster farm and to the rest of wall in jeopardy of collapse.
24	Fluvial	Ongoing	Flooding of haunches, springs, inadequate ditch.
25	Fluvial	Ongoing	Flooding of haunches, springs, inadequate ditch. Marley Lane, Chislet.
26	Fluvial	Ongoing	Flooding of haunches due to an inadequate ditch, Marley Lane, Hoath.
27	Fluvial	Ongoing	Discharge from banks, inadequate ditch aggravated by springs. C198 Hoath Road and Tile Kiln Farm.
28	Groundwater	Ongoing	Road flooding due to springs - no proper drainage. Bredland Lane, Westbere.
29	Highway	Ongoing	Road flooding from land and properties. Unclassified road, Westbere.
30	Highway	Ongoing	Flooding of bridge due to undersized bridge portal. C205 Stodmarsh.
31	Highway	Ongoing	Level road, with rises either side, floods, no point to discharge. C203, Grove Road, Sandpits.
32	Fluvial	Ongoing	Road flooding, caused by Nailbourne, here in ownership of Church Commissioners. C204 & unclassified roads at Ickham.

33	Fluvial	2000	Roads flood due to Nailbourne, intermittent watercourse at Old Palace Road, Patrixbourne.
34	Fluvial	2000	Road flooding at the ford and small bridge, caused by Nailbourne in heavy spate. Shepherds Close Road & C203 Patrixbourne.
35	Fluvial	2000	Road flooding at the ford and small bridge, caused by Nailbourne in heavy spate. Shepherds Close Road & C203 Patrixbourne.
36	Fluvial	2000	Road flooding due to Nailbourne in heavy flood. Mill Lane & Bridge House, Bridge.
37	Highway	Ongoing	Road flooding due to natural discharge and raising of road. C206, Adisham Downs.
38	Highway	2000	Road flooding, Rose Lane, Bishopsbourne.
39	Fluvial	2000	Road flooding from Nailbourne, B2065 Black Robin Lane to Brickbat, Barham.
40	Highway	2000	Road flooding, B2065 Out Elmsted Lane, Barham.
41	Fluvial	2000	Road flooding C195, The Street, Barham. From Nailbourne.
42	Fluvial	2000	Road flooding from Nailbourne. Temporary bridge erected after depth exceeded 6 inches.
43	Fluvial	2000	Road flooding from Nailbourne. South Barham Road at Barham and Derringstone.
44	Fluvial	2000	Road flooding from Nailbourne. South Barham Road at Barham and Derringstone.
45	Highway	2000	Flooding of an unclassified road at Woolage Green.
46	Fluvial	2000	Road flooding due to Nailbourne where it flows through an inadequate culvert.
47	Fluvial	2000	Nailbourne, intermittent river flooding road. Surcharge from springs. Little Buckett, Bodsham.
48	Fluvial	2000	Road flooding from intermittent underground river - Nailbourne. Yocketts Farm, Ansdore Road.
49	Fluvial	2000	Road flooding from intermittent underground river - Nailbourne. Ansdore Road.
50	Fluvial	2000	Road flooding from Nailbourne, intermittent river, surcharge from springs. Church Lane, Petham.
51	Fluvial	2000	Road flooding from Nailbourne, Intermittent underground river. Garlinge Green Road.

52	Fluvial	2000	Road flooding from Nailbourne, intermittent underground river. Kenfield Road, Garlinge Green.
53	Fluvial	2000	Road flooding due to intermittent underground stream, Nailbourne. Watery Lane.
54	Fluvial	2000	Road flooding due to intermittent underground stream, Nailbourne. Petham Road, Swarling Manor and Watery Lane.
55	Fluvial	2000	Road flooding due to intermittent underground stream, Nailbourne. Petham Road, Swarling Manor and Watery Lane.
56	Fluvial	2000	Road flooding from Nailbourne, Mystole Road, Chartham. Intermittent underground river.
57	Sewer	2000	River Stour in flood causes surcharging of sewer, Shalmsford Street, Chartham.
58	Fluvial	2000	Riverside, Chartham floods when River Stour is in flood.
59	Fluvial	2000	Road floods, unclassified road called Tonford Lane, Thanington.
60	Fluvial	2000	Road floods, unclassified road called Hassell Reach, Thanington.
61	Groundwater	2000	Springs cause road flooding. Primrose Lane, Chartham Hatch.
62	Groundwater	2000	Flooding of C2020, Danstead Lane, Chatham Hatch, due to springs and runoff from orchards.
63	Surface Water	2000	Water run-off from adjacent fields captured by retaining wall in gardens.
64	Surface Water	Ongoing	Severe external flooding from steep meadow. Vestigial ditch unable to intercept. Some internal flooding possible but no actual records.
65	Sewer	Ongoing	Severe flooding/waterlogging of cemetery mainly due to under-capacity/defective SW sewer. Collapsed length now repaired. Southern Water aware of capacity problem - upgrade not believed to be imminent.
66	Surface Water	2000	Water flowing down Salisbury Road from blocked culvert.
67	Highway	2000	Deep water flooding to road and properties due to blocked drainage channel.
68	Sewer	2000	External flooding due to blocked SW sewer.
69	Fluvial	2000	Flooding of caravan park due to neglected ditches.
70	Fluvial	2000	Very severe external flooding due to blocked culvert

71	Surface Water	2000	Severe garden flooding due to absence of land drainage. Alleviated by installing gully in garden, culverted under road into ditch.
72	Surface Water	2000	Severe flooding to farm due to inability of ditch to discharge under the Thanet Way.
73	Highway	2000	Road flooding due to blocked culvert under Thanet Way.
74	Highway	2000	Road flooding due to inadequate ditch/culvert system.
75	Surface Water	2000	Garden flooding due to neglected private ditch.
76	Highway	Ongoing	Road flooding due to inadequate ditch/culvert system.
77	Surface Water	Ongoing	Flooding due to SW runoff.
78	Fluvial	2000	Culvert blockage.
79	Highway	2000	External flooding due to inadequate highway drainage/vestigial ditch system. Highway drainage since improved.
80	Sewer	2000	Foul water blockage/backing up. SW under capacity.
81	Highway	2000	Highway flooding possibly due to neglected ditch system. Since remedied.
82	Surface Water	2000	External flooding due to blocked allotment ditch. Since cleared.
83	Surface Water	2000	Culvert blocked, properties flooded.
84	Surface Water	2007 2000	Deep flooding to car park and surrounding streets. Numerous properties internally flooded. Flash flood exacerbated by problems at pumping station.
85	Highway	2000	External flooding due to inadequate road drainage.
86	Highway	2000	Road gully blocked. Water on road threatening properties.
87	Fluvial	2000	Minor stream fluvial flood
88	Surface Water	2000	Severe external flooding from blocked SW sewer taking flow from Reed Pond, to rear of properties.
89	Surface Water	2000	Water runoff from adjacent fields, internal flooding to ground floor flats. Subsequent land drainage works to divert flows are proving effective.

90	Surface Water	2000	Culvert blocked water flowing down to Salisbury and Beaconfield Rds.
91	Sewer	2000	Internal foul flooding due to under-capacity FW sewer. Non-return valves now fitted to alleviate issue.
92	Surface Water	2000	Property flooded water coming from next door's garden.
93	Surface Water	2000	Water entering gardens from stream uphill. Flooding also from blocked SW sewer behind properties on St Thomas' Hill.
94	Surface Water	2000	Gardens flooded by water runoff from adjacent allotments.
95	Surface Water	2000	External flooding from playing fields probably due to poorly maintained ditch. Ditch now cleared, school aware of responsibility.
96	Surface Water	2000	SW runoff and drainage under capacity.
97	Surface Water	2000	External flooding due to inadequate land drainage system.
98	Fluvial	2000	External/internal flooding to several properties due to surcharged SW sewer
99	Highway	2007	Surface water from road flooding driveways
100	Fluvial	2007	Flooding from suspected pump failure at Gorrel tank
101	Highway	Apr-00	Highway Flooding
102	Surface Water	9th February 2001	Surface Water Flooding
103	Surface Water	9th February 2001	Surface Water Flooding
104	Surface Water	23rd March 2001	Surface Water - Unknown Address
105	Surface Water	8th February 2001	Surface Water Canterbury Hill/Tyler Hill
106	Surface Water	4th April 2000	Surface water flooding in the surrounding area
107	Fluvial	Ongoing	Blean Common: flooding from ditches & culverts
108	Sewer	2011	Badgers Close: surcharging drains

109	Surface Water	Ongoing	Honey Hill: runoff from fields
110	Highway	Ongoing	Blean Hill: blocked road gullies
111	Highway	Ongoing	Tile Kiln Hill: runoff from fields
112	Surface Water	2001	Maydowns Rd. Garden & sun lounge completely flooded
113	Surface Water	4th April 2000	Chestfield Rd. Extensive external flooding
114	Highway	8th February 2001	Chestfield Rd closed by police due to flooding
115	Highway	2001	Molehill Rd/ Birkdale Close. Flooding in junction 3ft deep
116	Fluvial	Ongoing	Molehill Rd: Ditches/culverts vulnerable to blocking/overflowing
117	Surface Water	2001	Little Paddocks. Water 2" below airbricks
118	Surface Water	Nov-00	Cherry Orchard. Unspecified flooding
119	Surface Water	2001	Highgate Lodge, The Ridgeway. Internal flooding to 9" depth
120	Sewer & Drain	2000/2001	Foul flooding from drain and from sewage backing up. New large holding tank constructed by Southern Water to alleviate issue.